








BEN-YA INDUSTRIAL CO., LTD.

4F, NO.16, LANE 181, SEC.2, JIUZONG ROAD Taipei, Taiwan, R.O.C.
TEL: 886-2-27990822 FAX: 886-2-27978753 e-mail: benya@ms24.hinet.net

ISEKI CATALOGUE

Date: 2022/08/30

| SEQ. | PHOTO | OEM_NO/ITEM_NO | DESCRIPTION |
|------|---|-----------------------------|---|
| 1 |  | 41201-09650 HIK72BK-CWP0 | HINO HILUX CROWN WHEEL & PINION (11*43) |
| 2 | | IK175BK-PTR0 | ISEKI T1000 PISTON RINGS |
| 3 |  | DLA155P15 IK295BK-NZL0 | ISEKI T1500 NOZZLE |
| 4 | | IKB90BK-PTR0 | ISEKI T1550 PISTON RINGS |
| 5 |  | IKB90BK-PTN0 | ISEKI T1550 PISTON/PIN/CLIP |
| 6 |  | IK297BK-PTN0 | ISEKI T1700 PISTON / PIN/CLIP |
| 7 | | IK297BK-PTR0 | ISEKI T1700 PISTON RINGS |
| 8 |  | IKB19BK-SSK0 | ISEKI T900 SEAL KIT |



BEN-YA INDUSTRIAL CO., LTD.

4F, NO.16, LANE 181, SEC.2, JIUZONG ROAD Taipei, Taiwan, R.O.C.
TEL: 886-2-27990822 FAX: 886-2-27978753 e-mail: benya@ms24.hinet.net

ISEKI CATALOGUE

Date: 2022/08/30

| SEQ. | PHOTO | OEM_NO/ITEM_NO | DESCRIPTION |
|------|---|-----------------------------|---|
| 9 |  | IK057BK-GT30 | ISEKI TJ75 (E4DE-T) CYL HEAD GASKET (GRAPHITE) |
| 10 |  | IK918BK-PTR0 | ISEKI TL2500 / TL2300 PISTON RINGS (80*2*2*4) |
| 11 |  | IK570BK-PTR0 | ISEKI TL2800 / TL2900 PISTON RINGS STD (76.2*2*2*4) |
| 12 |  | 34550-47040 IK057BK-COL1 | ISEKI TRACTOR COLLAR |
| 13 |  | 34550-15000 IK057BK-COL0 | ISEKI TRACTOR COLLAR |
| 14 |  | 20489410 IK057BK-SSK0 | ISEKI TRACTOR SEAL KIT |
| 15 |  | IK349BK-PTR0 | ISEKI TS1610/ TS1910 PISTON RINGS |
| 16 |  | IK807BK-PTR0 | ISEKI TU13F PISTON RINGS STD (70*2.5*2.5*4) |




BEN-YA INDUSTRIAL CO., LTD.

4F, NO.16, LANE 181, SEC.2, JIUZONG ROAD Taipei, Taiwan, R.O.C.
TEL: 886-2-27990822 FAX: 886-2-27978753 e-mail: benya@ms24.hinet.net

ISEKI CATALOGUE

Date: 2022/08/30

| SEQ. | PHOTO | OEM_NO/ITEM_NO | DESCRIPTION |
|------|---|----------------|--|
| 17 |  | IKB19BK-PTR0 | ISEKI TU1700 / TU1900 PISTON RINGS STD (76*2*2*4) |